

Over the years, I've noticed quite a few Airflows without the rubber channel which is attached to the top of the door and runs part way down the sides. No doubt this gasket is designed to keep rain and dust out, reduce wind noise, and possibly assist in minimizing vibrations or door rattle. My own C2 suffered from a lack of this part, and I was discussing it with Dave Brand at the WPC Meet last year. Dave was kind enough to provide a McMaster Carr part number for this rubber channel. It's 8507K16, and at \$1.40 per foot it's a small investment for the above mentioned benefits. It works great! Thanks, Dave!

