

Car Serial Number	Hood Lock Ass'y	Hood Louver Bars	Grille Ass'y	Hood Ass'y	Hood Top Moulding
CU to body # CU1185				(LHD) Prime 481747	474060
CV to body # CV1007				Paint 481850	
CU from body # CU1185 to Car # 6597846				(LHD) Prime 481748	474060
CV from body # CV1007 to Car # 7010586				Paint 481851	
CU after car #6597846		(set) 485001 to		(LHD) Prime	484138
CV after car #7010586		485019	628315	485493	
CX (all)?		plus 485091		Paint 485494	
CU to car # 6593039		(Ass'y) 623267	628280		
CV to car # 7010123					
CU from #6593039 to # 6597846		(Ass'y) 628316	628315		
CV from #7010123 to # 7010586					
CU Coupes to car # 6594758					
CV Coupes to car # 7010205	470578				
<u>All CU Broughams</u>					
CU Coupes after car # 6594758					
CV Coupes after car # 7010205	480413				
<u>All 4-door cars</u>					
All CW Models	480413	486608 to 486627	Prime 633939	Paint 636030	484138

Confusing, isn't it? To continue quoting Bill:

"There are some other subtle ramifications to the varieties shown on the chart. There were three different grilles used, but in the first case, they do not change at the same point as the first louver change, although they do in the second case. Secondly, There are two different hood top mouldings, which change with the second louver change, but which by separation of the ornament (which does not change) would seem to bear no relation to the louvers. Third- The two early model louver set ups have later parts numbers than the later style louvers, which are numbered much lower. This is not the case with the top mouldings, which both have lower numbers, or with the grilles, which have higher numbers. Fourth, the CX cars all used the later version of all items, indicating late production in the model year, or else that they started out looking different from the CU's and CV's. Fifth, and last is the strange fact that the 2-door Broughams used different hood locks from the 4-door models, while the Coupes used first one and then the other variety!"

Incredible!