

Date: August 15, 2024
Location: London, ON
Meet No.: 59

ACA Judging Sheet

Year and Series	Owner
Serial No.	Color

Chassis	Standard	Judging Comments	Max Ded Corr. Cond. Total		
Axles	Unique, heavy duty, hypoid differential. Two-piece drive shaft	Check paint. Excessive grease/dirt= -1 ea. Leaks= -1 ea leak.	4	4	4
Hub caps	Chrome, louvered wheel disks with junior-size hubcaps; Chrysler script, no paint.	Ex: damaged= -1 ea; incorrect= -2 ea; missing=-2 ea. Total is for 4 wheels.	6	6	6
Muffler	One 18" x 6" round and one 34" x 6" round muffler	NOS are scarce. Check condition and type. Ex: wrong shape= -2	2	2	4
Shock absorbers	Four, Houdaille lever action shocks; painted black.	Ex: obvious leaks=-1 each, bad link joints= -1 each link; missing shock or link= -2 each.	4	4	4
Tires	Original 7.50-17 blackwall; whitewall tires optional.	Traditional appearance (deduct for wide tread, snow tires, obvious squat or under inflation); poor condition, or mismatched -1 each	4	4	6
Wheels	7.50-17 wire-spoked, 6 bolt.	Ex: wrong wheel= -2; incorrect stripe= -1; damaged/poor condition= up to -2; all each wheel.	4	4	4

Date: August 15, 2024
Location: London, ON
Meet No.: 59

ACA Judging Sheet

Year and Series	Owner
Serial No.	Color

Engine	Standard	Judging Comments	Max Ded Corr. Cond. Total		
Air cleaner	Dry type with polished cast aluminum connector and service decal.	Check for presence, correctness, completeness (filter element or oil bath), condition (paint, decal). Ex. missing decal= -1; wrong color= -1; missing filter or oil bath= -2.	4	3	4
Belt, fan	Original was red with notches, part 384267	Check for presence and condition. Ex: worn or frayed belt= up to -3; bent blades= -2.	1	1	3
Carburetor	Stromberg EE-3 painted wrinkle black; with chrome fittings and linkages.	Check for model and condition. Ex: manual choke= -2; wrong carb= -3.	5	5	4
Cylinder block	Black wrinkle paint	Check for obvious damage or defect; wrong color= -2; wrong series= -2; excessive dirt or grease= -1; core plug leak= -1 ea..	4	3	6
Cylinder head	Polished aluminum; thermostat housing and spacer polished aluminum; head bolts use chromed or polished stainless acorn nuts	Ex: wrong metal= -2; wrong color= -1; top water outlet= -3; leaks= -2.	3	2	6
Distributor	Unique vertically mounted distributor on top of head near carburetor.	Ex: Missing tag= -1; wrong dist= -4; missing or disconnected vac advance= -2	5	3	4
Fuel supply	Mechanical pump mounted on cylinder block, natural metal color with attached heat shield painted black; rubber flex hose from frame to fuel pump with crimped hose ends (no hose clamps); dual-action fuel/vacuum pump.	Check type, connections, shield, condition, leaks. Ex: clamps=-2; missing heat shield= -2; electric pump is acceptable if concealed.	4	4	5
Generator	Chrome brush cover	Check for correct generator and tag. Ex: alternator= -5; missing tag= -1.	4	4	4
Horns	Delco-Remy Klaxon K-33D, type 1955 (low note) and 1956 (high note), chrome bell caps; horn bodies black	See photo. Ex: wrong horn= -2; nonworking= -1; poor finish= -1, all each.	4	4	4
Hoses / clamps	Straight-style hoses only (no flex hoses); double-wire clamps on all radiator hoses; period-correct clamps on heater hoses; flat style clamps on all vacuum hoses.	Ex: wrong hose type= -1 ea; wrong clamps= -1 ea; rotted or leaky hoses= -2 ea.	6	6	6

Date: August 15, 2024
Location: London, ON
Meet No.: 59

ACA Judging Sheet

Manifolds Both manifolds porcelain. All have brass nuts.

Mfr data plate Most Lebaron cars had only the job number on the data plate. Lebaron ID on firewall.

Oil filter Vertical disposable Purolator-type, painted black, chromed straps; both inlet and outlet on bottom end.

Starting motor Delco-Remy

Steering tube Satin chrome finish

Voltage cutout / regulator Mounted on generator; cover chrome

Water pump Painted black. CW pump has a unique chrome plate boss on the front of the pump, behind the pulley.

Year and Series	Owner
Serial No.	Color

Ex: wrong finish= -2 per manifold; wrong nuts= -2 max; poor condition or damaged= -2 ea.

646

Ex: missing= -2; illegible or wrong for car= -1

222

Check for presence and leaks. Ex: wrong inlet/outlet placement= -0; wrong mounting location= -1; wrong type filter= -2.

333

Ex: wrong starter= -4; wrong solenoid= -3; greasy or rusty= -2; imperfect operation= -3

444

Check portion under hood for color and condition.

222

Check for type and location. Location should be consistent with generator type. Ex: wrong type= -2; wrong location= -1.

223

Ex: wrong pump= -2, unpainted or wrong color= -1; leaking= -2

222

Date: August 15, 2024
Location: London, ON
Meet No.: 59

ACA Judging Sheet

Year and Series	Owner
Serial No.	Color

Exterior	Standard	Judging Comments	Max Ded Corr. Cond. Total		
Bumpers / guards / gravel deflectors	Correct bumpers and guards for year model; 34 and 35 have 4 bars. Rear gravel deflectors (if so equipped) painted body color.	Ex: missing guards= -1; wrong guards= -1; missing badge= -1 (all ea); poor chrome= up to -2 ea; wrong finish bracket or back bar=-2 F or R. Upside down: bumper= -1 ea or guards= -1 total.	8	8	8
Running boards	Unique cast aluminum with step pads surrounded by stainless steel trim; welt at body.	Check for correctness and condition. Ex: missing chunks= -3 ea side; wrong or missing molding or trim= -2 ea side	8	8	6
Top	Waterproofed fabric	Wrong type top panel= -4; check appearance, condition, evidence of leaks.	4	4	4
Window frames	One-piece curved glass with special frame. Front vent divider was chrome; frame black. Rear quarter vent frame and divider were chrome.	Check for correctness, poor or deteriorated finish, inside rot, bubbling, correct rubber and corner inserts.	8	8	8

Date: August 15, 2024
Location: London, ON
Meet No.: 59

ACA Judging Sheet

Year and Series	Owner
Serial No.	Color

Interior	Standard	Judging Comments	Max Ded Corr. Cond. Total		
Clock	Waltham 8-day on glove box door; some Chrysler accessory clocks were available.	Check presence and appearance, if so equipped.	1	1	1
			<div></div>	<div></div>	<div></div>
Dashboard	Painted black or custom-ordered color.	Check finish, components, correctness, condition	5	5	5
			<div></div>	<div></div>	<div></div>
Floor cover (mat)	Sedan: brown or custom mouton front and rear; limousine: black mouton front, brown or custom rear	Deduct 5 for wrong floor covering.	5	5	5
			<div></div>	<div></div>	<div></div>
Garnish moldings	Painted color to order; slotted screws, chrome or polished stainless, with cup washers. Wide satin chrome extension below with zebra-stripe wood inlay, or custom	Ex: excessive wear= -1 each frame, wrong finish= -1 each. Max ded is for all frames.	6	6	6
			<div></div>	<div></div>	<div></div>
Handles / knobs / switches	Most butler (satin) chrome. Bowes limousine had Dirilyte (gold) on doors. Cat-eye lighter knobs.	Check correctness and condition. Ex: wrong handles= -1 ea; incorrect or damaged escutcheons= up to -1 ea; poor plating= -1 ea; wrong switch= -1;	8	8	8
			<div></div>	<div></div>	<div></div>
Headliner	Cloth	Check condition and correctness.	4	4	4
			<div></div>	<div></div>	<div></div>
Instruments	Most white background with black lettering / numerals; bezels satin chrome. Bowes car silver faces.	Check correctness and condition. Ex: missing heat gauge= -2; missing speedo= -3; damaged or discolored face= -1 ea. Max ded is 3 each cluster.	6	6	6
			<div></div>	<div></div>	<div></div>
Mirror	Bracket satin chrome, attached to inside of windshield frame. Beveled mirror. Exterior mirrors were added by dealers or other retailers.	Check condition and correctness.	2	2	2
			<div></div>	<div></div>	<div></div>
Panels, straps, rails, visors	Visors hung with stationary brackets at both ends finished with satin chrome. No robe rail.				
Pedals / shift lever	Pedals, shift boot, heel pad black, shift knob brown or black with chrome ratchet motif; shift lever satin chrome.	Ex: wrong knob= -2, excessive wear or damage= -1 ea occurrence; wrong or bad finish -1 ea. Brake and clutch pedal pads different colors= -2.	3	3	3
			<div></div>	<div></div>	<div></div>

Date: August 15, 2024
Location: London, ON
Meet No.: 59

ACA Judging Sheet

Radio Head mounted in unique center dash bezel; finished in satin chrome

Seats (cushion / back) Front: Wood-framed; upholstery was wool (sedans) or black leather (limos) or custom; rear seat arm upholstered in wool broadcloth or custom; courtesy lights on rear seat base corners.

Steering wheel / post Steering wheel black 3-spoke or stainless banjo style, post dull chrome. Wheel 18" diameter.

Year and Series	Owner
Serial No.	Color

Ex: wrong (period inappropriate) radio= -1; head only= -2.	2	2	2
	<div></div>	<div></div>	<div></div>

Ex: wrong pleats and design= -2 ea cushion; wrong fabric= up to -3 total; tears, wear-through= -2 per cushion; excessive dirt or stain= up to -4 total	8	8	8
	<div></div>	<div></div>	<div></div>

Check correctness and condition. Ex: wrong finish= -2; cracks or breaks= up to -3 off; wrong or damaged horn button= up to -2; wrong post finish= -2.	4	5	4
	<div></div>	<div></div>	<div></div>